Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/15015SE-5074/1

Work Order Type: Weatherization

Audit Name: NA

CLIENT INFORMATION

Client Name: Address:

Client ID: 15015SE-5074

Alt. Client ID: Meigs

<u>AGENCY INFORMATION</u>

Agency: Southeast Tennessee Human Resource Agency Agency Phone: (423) 949-2191

Address: 312 Resource Rd. **Fax:** (423) 949-4023

Agency Contact: Gaskins, Glenn Work Phone:

Cell Phone: (865) 679-8303

Email Address: amerispechome20@bellsouth.net

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Site Built

Home built in 1956 per client. Lead Safe Weatherization protocol applies.

			Components					Inspected	
2. Sea ceiling 3. Pan backs about	atherstrip D1 Door at Laun Il all joints in door frame ar plywood seams at Laund It lel over and seal unused d It up to bathroom tub. Air info foaming/sealing and enclo	nd trim on ry. door openi filtration frosing area	ng at n om atti	niddle bedro	om. Ope	ning			
				Estimated Actu			Actual	<u>1/</u>	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
0 Miscellaneous S	u Infiltration Reduction	Each	1						
Other Detail									
			Measur	e Sub Total:]	Sub Total:		
Comment Fill atti Rewor	ic Ins. R-38 ic ceiling to R38 blown cell	lulose 110		Componen	to A++io				
to spe	k and insulate/weatherstrip	p attic acc	ess. İn	t. stall insulati		Adhere)	Inspected	
	k and insulate/weatherstri cifications of Southeast W	p attic acc	ess. İn	t. stall insulati	on dam.	Adhere	e Actual	Inspected	
# Material / Labor		p attic acc	ess. İn	t. stall insulati eld Guide.	on dam.	Adhere		Inspected	
	cifications of Southeast W	p attic acc eatherizat	ess. In tion Fie	t. stall insulati eld Guide. <i>Estimated</i>	on dam.		Actual		
	cifications of Southeast W **Description / Comment** Attic Insulation - Blown	p attic acc eatherizat	tion Fie	t. stall insulati eld Guide. <i>Estimated</i>	on dam.		Actual		
1 Insulation	cifications of Southeast W **Description / Comment** Attic Insulation - Blown	p attic acc eatherizat	tion Fie	t. stall insulati eld Guide. <i>Estimated</i>	on dam.		Actual		
1 Insulation	cifications of Southeast W **Description / Comment** Attic Insulation - Blown	p attic acc eatherizat	tion Fie	t. stall insulati eld Guide. <i>Estimated</i>	on dam.		Actual		
# Material / Labor 1 Insulation Other Detail	cifications of Southeast W **Description / Comment** Attic Insulation - Blown	p attic acc eatherizat <i>Units</i> SqFt	ess. In tion Fie	t. stall insulati eld Guide. <i>Estimated</i>	on dam.	Qty	Actual		

Client Name: Client ID: 15015SE-5074 Alt. Client ID: Meigs Work Order (Bid Form)

Work Order Name: WO/15015SE-5074/1 Report Run On: 4/29/2010

Measure 3 Prac (Wal	tice Lead Safe Weather	rization		Componen	ts		ı	Inspected
follow re Painting	pre-1978. Follow lead sequirements of EPA Lead Contractor to adhere to Contractor to adhere to	d -Based F 4 step re	Paint R quirem	enovation, I ents of WA	Repair ar P ARRA rm	nd	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	Equipment	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
						_		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Gran	d Total:	